

*****2023.4.27 CVT10 V1.1.0.0.STD*****

[Supporting Software]

NovaLCT V5.4.0 or later

[New Features]

None

[Improvements]

None

[Changes]

None

[Bug Fixes]

1. Fixed some bugs.

[Notes]

1. Users must use the USB Type-B port on the front panel to upgrade the firmware program.