

[Supporting Software]

NovaLCT V5.7.1 or later

[New Features]

1. Added support for bit error detection of Ethernet port.

[Improvements]

1. Optimized TCP transmission speed to enhance interaction efficiency.

[Changes]

None.

[Bug Fixes]

1. Fixed the issue with abnormal flickering pixels.

[Notes]

None.