

[Supporting Software]

NovaLCT V5.7.1 or later

[New Features]

1. Added the feature to accelerate the sending of calibration coefficients.
2. Added an enhanced mode for optical port.

[Improvements]

1. Enhanced source compatibility.
2. Optimized optical port compatibility.

[Changes]

1. Modified the menu logic for mapping.
2. Changed the minimum topology width to 128.

[Bug Fixes]

1. Fixed the issue of abnormal screen offset reading on the configuration interface in NovaLCT.
2. Fixed the issue of parameters not saved in fiber converter mode.
3. Fixed the issue of parameters on the LCD home screen not saved.
4. Fixed the backup-related issues.
5. Fixed cascading issues.

[Notes]

None.